
DATASHEET




Art. No.: K3930V42

Earthing Bar for Vertically Mounting in 42U Network Cabinets

Insulator 1





- Mounting via 4 supporting insulators at the sided round holes of the 19" profiles
- Also suitable in combination with vertically blind panel 691251/691251TS
- For mounting in server cabinets the installation an an additional 19" profile is recommended (for additional notices see text lowest text on this page)
- Scope of delivery:
 - 1 x Cu Earthing bar E-Cu57 DIN46433, 1800 x 15 x 5 mm
 - 12 x Busbar terminal for cables 1.5 .. 16 qmm
 - 4 x Supporting insulator
 - 8 x Thread bolt M6 x 25
 - 8 x Washer
 - 8 x Nut M6, self-locking
- Earthing cable K2303.x not included in delivery (see accessories)

Insulator 2

Mounting Instructions for EFB Network Cabinets:

Please hold on the following steps:

- Assemble the 4 insulators with 2 thread bolts each, use an Inbus tool H3
- Place the 4 insulators in the prepared holes in the copper bar, fix them with washers and nuts, but do not tighten the screws hardly, to make mounting onto the 19" profile easier. Note: the screws are self-locking types, later loosening of screw is not possible.
- Place the earthing bar at the 19" profile in a way, that bolts are positioned in the holes as following (see picture):

Insulator 3

- Bolt insulator 1 (=1. from upside): 1. round hole from upside in installed 19" profile (ca. U 42)
- Bolt insulator 2 (=2. from upside): 21. round hole from upside in installed 19" profile (ca. U 26)
- Bolt insulator 3 (=3. from upside): 34. round hole from upside / 21. RH from downside in installed 19" profile (ca. U 17)
- Bolt insulator 4 (=1. from downside): 1. round hole from downside in installed 19" profile (ca. U 1)
- If all 4 bolts of the insulators are sitting correctly in the 19" profile, mount the inner washers and nuts and tighten them
- For fixing the rail finally now also tighten outer nuts
- · Set the busbar terminal onto the earthing bar, after inserting the earthing cable fix them using the terminal screw

Mounting Notes for EFB Server Cabinets:

Side-mounting at the 19" profile server cabinets is not intended because of the vertically traverses for increasing the max. load of the cabinet. However, there are 2 workarounds:

- Retroffitting of one or two additional 19" profiles in server cabinet (Art.-No. 691678, set of 2)
- Remove one of the 4 vertically traverses half-heigt at the 19" profile. ATTENTION: this causes a
 lost of max. load on the affected profile, so think about the intended load of the cabinet before
 applying this method





Art.No.	K3930V42	File	K3930V42_NEU.indd				
Description	Earthing Bar for Vertically Mo	Earthing Bar for Vertically Mounting in 42U Network Cabinets					
Created	Date	Last revision	Date	Proved	Date		
Frederik Dotzki	23.09.2013	ВТ	23.09.2013	MN	13.02.2014		

DATASHEET





detail view: mounted supporting insulator and busbar terminal



Recommended accessory: earthing cable 6 mm 2 with ring cable lug \oslash 6 mm and wire end sleeve

Art.-No. K2303.x (x = length 0.5 / 1 / 1.5 / 2 m)

Order data

Art. No.	Туре			
K3930V42 Earthing Bar for Vertically Mounting in 42U Network Cabinets				
Accessories:				
Art. No.	Туре			
K2303.x	Earthing cable 6 mm ²	A		

Art.No.	K3930V42	File	K3930V42_NEU.indd			
Description	Earthing Bar for Vertically Mounting in 42U Network Cabinets					
Created	Date	Last revision	Date	Proved	Date	
Frederik Dotzki	23.09.2013	BT	13.02.2014	MN	13.02.2014	